

Appendix 3



Certificate No. CTK20160321001EMC

Models

X463H21G, X463X11G, X463X21G, 50F2H00, 50F5H00A, 50F3H00AP, 50F4H00SA, 50F1H00, 50F2X00, 50F5X00A, 50F3X00AP, 50F4X00SA, 50F1X00, 60F2H00, 60F5H00A, 60F3H00AP, 60F4H00SA, 60F1H00, 50F2U00, 50F5U00A, 50F3U00AP, 50F4U00SA, 50F1U00, 60F2X00, 60F5X00A, 60F3X00AP, 60F4X00SA, 60F1X00, 52D2000, 52D3000AP, 52D4000SA, 52D1000, 52D2H00, 52D5H00A, 52D3H00AP, 52D4H00SA, 52D1H00, 52D2H0L, 52D1H0L, 52D1X0L, 62D2000, 62D5000A, 62D3000AP, 62D1000, 62D2H00, 62D5H00A, 62D3H00AP, 62D4H00SA, 62D1H00, 50F0Z00WW, 50D0Z00WW, X264H11G, 403059, 413460, Type SP 1000A, 413196, SP1000E, 407165EXP, 407166, SP100LE, 412477, TYPE 2285, 406212, SP 5200HA, 406683, SP5200HE, 406685, SP 3400LC, SP 3400LA, 406464, SP3400LE, SP3400HC, SP3400HA, 406465, SP3400HE, 406522, SP 3500XC, SP 3500XA, 406989, SP3500XE, SP3400, 308571, SP 3400H, 308572, SP 3400L, 308857, SP 200C, 430707, SP201HA, 407258, SP 201HE, 407254, SP 200HE, 407262, SP 110C, SP 110Q, SP 310C, 403074, TYPE 120, 402089, TYPE SP4100, 402810, SP 4500LA, 407321, SP 4500LE, SP 4500LS, 407322, SP4500A, 407319, SP 4500E, SP 4500S, 407320, SP 4500HA, 407316, SP4500HE, SP4500HS, 407312, 407317, SP 4500L, SP 4500, SP 4500H, 01279001, 52123601, 01279101, 52123602, 01279201, 52123603, SCX-D4200A, SF-D560RA, MLT-D109S, MLT-D1092SSCX-D4725A, MLT-D108S, MLT-D1082S, ML-D3050A, ML-D3050B, SCX-D5530A, SCX-D5530B, ML-D3470A, ML-D3470B, MLT-D206S, MLT-D206L, MLT-D208S, MLT-D2082S, MLT-D208L, MLT-D2082L, ML-D2850A, ML-D2850B, MLT-D209S, MLT-D2092S, MLT-D209L, MLT-D2092L, ML-2250D3, ML-2250D5, SCX-4720D3, SCX-4720D5, ML-D1630A, ML-2150D8, ML-2550DA, MLT-D1053S, MLT-1053L, MLT-D105S, MLT-D1052S, MLT-D105L, MLT-D1052L, MLT-D104S, MLT-D1042S, MLT-D1043S, MLT-D103S, MLT-D103L, MLT-D205S, MLT-D205L, MLT-D205E, MLT-D101S, ML-3560D6, ML-3560DB, MLT-D308S, MLT-D308L, ML-D4550A, ML-D4550B, MLT-D305S, MLT-D305L, MLT-D117S, MLT-D102L, MLT-D115L, MLT-D116S, MLT-D116L, MLT-R116, MLT-D111S, MLT-D111L, MLT-D111E, MLT-D203S, MLT-D203L, MLT-D203E, MLT-D203U, MLT-D204S, MLT-D204L, MLT-D204E, MLT-D204U, MLT-R204, ML-1710D3, SCX-D4200A, ML-1710D3, X3119, ML1610D3, 2010D3, MLT-D307S, MLT-D307L, MLT-D307E, MLT-D307U, MLT-D309S, MLT-D309L, MLT-D309E, SCX-6320D8, SCX-D6555A, SCX-R6555A, MLT-D201S, MLT-D201L, MLT-D112S, MLT-D118S, MLT-D118L, MLT-R118, CLT-K404S, CLT-C404S, CLT-M404S, CLT-Y404S, CLT-K406S, CLT-C406S, CLT-M406S, CLT-Y406S, CLT-K403S, CLT-C403S, CLT-M403S,

CERTITEK TESTING AND CERTIFICATION LTD

Staples Business Park, 1000 North Circular Road London, NW2 7JP, U.K

☎ + 86 20 3921 1670 ☎ + 86 20 3921 1640 ✉ Info@certitek.co.uk 🌐 www.certitek.co.uk v2.0